

RATES FOR SERVICE*

Whole-House Inspection Pricing:

 $0-999 \ ft/2 = 435.00 $2500-2999 \ ft/2 = 545.00 $4500-4999 \ ft/2 = 675.00 $1000-1499 \ ft/2 = 470.00 $3000-3499 \ ft/2 = 570.00 $5000-5999 \ ft/2 = 725.00 $1500-1999 \ ft/2 = 495.00 $3500-3999 \ ft/2 = 595.00

6000+ ft/2 - Inquire for quote - price dependent on ft/2 and systems involved (number of HVAC units, addt'l kitchen, etc.).

Property age fees

0 to 39 years = no additional fee - 40 to 74 years = \$45.00 - 75 to 99 years = \$100.00 - Over 100 years = \$150.00

Fee for distance - 0-39 miles = no fee - 40-60 miles = \$25.00 - over 60 miles = Call (based on distance from office)

Re-inspection after repairs - \$275.00 Pool Inspection - \$375.00 Hot Tub/Spa - \$175.00

Detached Garage/Building - \$85.00 single story - \$150.00 two story (price increases with finished space/HVAC, etc.)

Termite Inspection (NCWDIR) - \$95.00 Pre-Drywall Inspection – Slab \$420.00/Crawl Space \$475.00

Radon Test – with home inspection - \$150.00 / without home inspection - \$175.00

Mold Test (Swab/Tape) Basic Package - \$385.00 Indoor Air Quality Basic Package - \$435.00

Chimney – Level 2 \$315.00 Chimney - Level 2/w sweep \$375.00 Gas Log Service/Direct Vent Fireplace - \$300.00 Chimney Level 2 required for RE transactions – Level 2 w/sweep required for wood burning chimneys

HVAC Diagnostic Inspection (performed by licensed tech) – Inquire for quote

Water Analysis – FHA/VA/HUD Panel (Performed In-House) - \$200.00 – 3-5 business days for report

Well & Septic Inspections (Typically performed together – for well only, consult customer service for a quote)

Well Inspection w/Lab Analysis - Bacterial Analysis: \$175.00 (It takes approximately 3-5 business days to receive these results from the lab)

Well Inspection w/Lab Analysis - FHA/VA/HUD FULL PANEL: \$250.00 (It takes approximately10 business days to receive these results from the lab).

Conventional or Pump Septic System: \$395.00 (includes excavation) - 50-75 miles add \$115.00 distance fee.

An additional fee of \$115.00 will assessed if the Inspector has to use the flushable Transmitting Detector Device to locate the septic system.

*Rates subject to change without prior notice

R.230103